



































GWR 'Ordinary' corridor coaching stock

| | | | | | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1174 | 1433 | 1593 | 2366 | 2392 | 2552 | 3941 | 4312 | 4765 | 5177 | 6017 | 6059 | 6203 | 6940 | 7758 | 8607 | |
| 1174 | 1433 | 1593 | 2366 | 2392 | 2552 | 3941 | 4312 | 4765 | 5177 | 6017 | 6059 | 6203 | 6940 | 7758 | 8607 | |
| 1174 | 1433 | 1593 | 2366 | 2392 | 2552 | 3941 | 4312 | 4765 | 5177 | 6017 | 6059 | 6203 | 6940 | 7758 | 8607 | |
| 1174 | 1433 | 1593 | 2366 | 2392 | 2552 | 3941 | 4312 | 4765 | 5177 | 6017 | 6059 | 6203 | 6940 | 7758 | 8607 | |
| 3684 | 6446 | 6447 | 6459 | 6580 | 1453 | 4161 | 6859 | 6112 | 7062 | 806 | 1082 | 1085 | 6861 | 7314 | 9579 | 9580 |
| 3684 | 6446 | 6447 | 6459 | 6580 | 1453 | 4161 | 6859 | 6112 | 7062 | 806 | 1082 | 1085 | 6861 | 7314 | 9579 | 9580 |
| 3684 | 6446 | 6447 | 6459 | 6580 | 1453 | 4161 | 6859 | 6112 | 7062 | 806 | 1082 | 1085 | 6861 | 7314 | 9579 | 9580 |
| 3684 | 6446 | 6447 | 6459 | 6580 | 1453 | 4161 | 6859 | 6112 | 7062 | 806 | 1082 | 1085 | 6861 | 7314 | 9579 | 9580 |
| G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R |
| G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R |
| G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R |
| G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R | G W R |
| FIRST | FIRST | FIRST | FIRST | FIRST | FIRST | FIRST | FIRST | FIRST | FIRST | FIRST | FIRST | FIRST | FIRST | FIRST | FIRST | FIRST |
| THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD |
| THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD |
| THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD |
| THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD |
| THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD | THIRD |
|  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |
|  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |  |
| GUARD | GUARD | GUARD | GUARD | GUARD | GUARD | GUARD | GUARD | GUARD | GUARD | GUARD | GUARD | GUARD | GUARD | GUARD | GUARD | GUARD |
| GUARD | GUARD | GUARD | GUARD | GUARD | GUARD | GUARD | GUARD | GUARD | GUARD | GUARD | GUARD | GUARD | GUARD | GUARD | GUARD | GUARD |

In vertical blocks of four

1174 K38 Full Brake 1926
 1433 D125 57' Brake 3rd 1937
 1593 D124 61' Brake 3rd 1937
 2366 D46 56' Toplight Brake 3rd 1910
 2392 D49 57' Toplight Brake 3rd 1911
 2552 C29 70' Toplight 3rd 1909/13
 3941 C32 70' Toplight 3rd 1914
 4312 C70 61' Corridor 3rd 1936
 4765 C54 59' BE Corridor 3rd 1925/29
 5177 C54 59' Corridor BE 3rd 1925/29
 6017 E137 61' 1929 CRE Comp
 6059 E155 60' Corr Comp 1937
 6203 E127 58' BE Corr Comp 1914
 6940 E98 57' Toplight Corr Comp 1914
 7758 E93 70' Toplight Corr Comp 1912/13
 9607 H38 61' RC end kitchen

Second block

3694 C31 57' Toplight Corr Comp 1911/13
 6446, 6447 E140 61' B set 1930/31
 6459, 6580 E140 61' B set 1930/31
 1435 C73 61' Corridor 3rd 1937
 4161 C71 60' Centre Corridor 1936
 6859 E152 61' Brake Comp 1936
 6112 E155 60' Corr Comp 1937
 7062 E159 61' Brake Comp 1938
 806 L18 TPO
 1082, 1085 C77 61' Corridor 3rd 1938
 6861 E152 61' Brake Comp 1936
 7314 E158 60' Corr Comp 1938
 9579,958 H33 58' BE RC 1925 central kitchen